

---

Subject: Re: Computer Overheating.  
Posted by [Nineball](#) on Sun, 12 Feb 2006 01:02:28 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

That is a Socket 775, which means that it is a Prescott-core P4.  
That kind of temperature is normal for a Prescott, nothing big to worry about, although I would really recommend getting Arctic Silver 5 and a better heatsink.

---